

Midas Auto & Tire 618 Lake St Nelson, BC V1L 4C8 +1 250-354-4866 www.midas.com

Date	10/18/2021	Vehicle	2016 Subaru Crosstrek
Customer	Carrie Clark	License Plate	BC JF230D
		Odometer	62,653 km
Repair Order	211018022	VIN	JF2GPABC7GH237931

Digital Midas Touch Vehicle Inspection



Priority Recommendations							
Inspection Point		Finding/Recommendations					
			-				
Maintenance: These items are recommended to increase the life of your vehicle and to lower the cost of ownership							
Brake Fluid Level / Condition		Last completed 55,564. Next due 103,654 Finding: Brake fluid flush as per scheduled maintenance Recommendation: Flush brake fluid to ensure safe operation of brake system.					
Midas Courtesy Check 1		Finding/Recommendations					
Is the License Plate Registration Current?	Yes	 Image: A second s					
Are All Dash Warning Lights Off?	Yes	 Image: A set of the set of the					
Are All Exterior Lights Working?	Yes	×					
Horn Working OK?	Yes	~					
Wipers 🗸							
Hood/Hatch supports							
Engine Air Filter		~					

<

Cabin Air Filter

*** The cabin Filter is what cleans the air that you breathe inside the car. It can contain mold, mildew and debris. This can degrade the air quality in the cabin of the vehicle.

Battery/Cables

Cooling System Hoses			
Midas Courtesy Check 2			Finding/Recommendations
Oil Condition prior to Oil Service?		 Image: A second s	
Power Steering Fluid Level / Condition		 Image: A start of the start of	
Transmission Fluid Level / Condition		 Image: A start of the start of	
Coolant Level / Condition		~	
Steering System		 	
Shocks and Struts		 	
Exhaust System		 	
Driveline		 	
Spark Plugs		 	
Timing Belt		~	
Fluid Leaks	Yes	✓	
Midas Courtesy Check 3			Finding/Recommendations
Left Front Tire Condition		 Image: A second s	
Left Rear Tire Condition		×	
Right Rear Tire Condition		 Image: A start of the start of	
Right Front Tire Condition		 Image: A second s	
Left Front Tire Pressure		✓	
Left Rear Tire Pressure		~	
Right Rear Tire Pressure		~	
Right Front Tire Pressure		~	
Wheel alignment ok?	Yes	~	

Keith Nickason, A Certified Technician has completed this inspection; it reflects the vehicle's condition on this day and does not imply a warranty on the items checked. This inspection should only be used as an aid. This inspection does not mean that there were no other problems, but only what we noticed or what appeared at the time of inspection. Certain items may need further inspection to determine the extent of damage and cost.